



specbos 1211-2 Firmware Changelog

V3.4.12 (18.03.2021)

new parameter to signalize, that straylight correction matrix is to be used

V3.4.11 (08.12.2020)

- bug in new fault pixel function -> fixed

V3.4.10 (04.12.2020)

- neighboring fault pixel were not possible -> fixed

V3.4.9 (16.11.2020)

reference measurements with integration time at split time were not correct -> fixed

V3.4.8 (29.10.2020)

- *meas:compdark now uses the average setting instead of fixed average=1

V3.4.7 (26.05.2020)

- unexpected behavior, when pulselength of a flash light was set to more than 2200us (*para:flash) -> fixed

V3.4.6 (05.03.2020)

- Sync measurement was not using integration times down to min_tint -> fixed

V3.4.4 (13.05.2019)

Sync measurement was not working (since V3.4.0) -> fixed

V3.4.0 (25.10.2018)

- Support for new detector S11155

Internet: www.jeti.com

E-Mail: sales@jeti.com